

Need for Optimal Distributed Measurement of Cumulative Quantities Explains the Ubiquity of Absolute and Relative Error Components

Hector Reyes, Jeffrey Escamilla, Ethan D. Kish,
Aaron D. Brown, and Vladik Kreinovich
Department of Computer Science, University of Texas at El Paso
El Paso, Texas 79968, USA
hareyes2@miners.utep.edu, jescamilla2@miners.utep.edu,
edkish@miners.utep.edu, adbrown3@miners.utep.edu,
vladik@utep.edu

1. Need for distributed measurements

- In many practical situations, we are interested in estimating the value x of a cumulative quantity; e.g, we want to estimate:
 - the overall amount of oil in a given area,
 - the overall amount of CO₂ emissions, etc.
- Measuring instruments usually measure quantities in a given location.
- Thus, they measure local values x_1, \dots, x_n that together form the desired value $x = x_1 + \dots + x_n$.
- So, a natural way to produce an estimate \tilde{x} for x is:
 - to place measuring instruments at several locations,
 - to measure the values x_i in these locations, and
 - to add up the results $\tilde{x}_1 + \dots + \tilde{x}_n$ of these measurement:

$$\tilde{x} = \tilde{x}_1 + \dots + \tilde{x}_n.$$

2. Need for optimal planning

- Usually, we want to reach a certain estimation accuracy.
- To achieve this accuracy, we need to plan how accurate the deployed measurement instruments should be.
- Use of accurate measuring instruments is often very expensive, while budgets are usually limited.
- It is therefore desirable to come up with the deployment plan that would achieve the desired overall accuracy within the minimal cost.
- This implies, in particular, that the resulting estimate should not be more accurate than needed.
- Indeed, this would mean that we could use less accurate (and thus, cheaper) measuring instruments.

3. Need for optimal planning (cont-d)

- In this talk, we provide:
 - a condition under which such optimal planning is possible, and
 - the corresponding optimal planning algorithm.
- The resulting condition explains why usually, measuring instruments are characterized by their absolute and relative accuracy.

4. How we can describe measurement accuracy

- Measurements are never absolutely accurate.
- The measurement result \tilde{x}_i is, in general, different from the actual (unknown) value x_i of the corresponding quantity.
- In other words, the difference $\Delta x_i \stackrel{\text{def}}{=} \tilde{x}_i - x_i$ is, in general, different from 0.
- This difference is known as the *measurement error*.
- For each measuring instrument, we should know how large the measurement error can be.
- In precise terms, we need to know an upper bound Δ on the absolute value $|\Delta x_i|$ of the measurement error.
- This upper bound should be provided by the manufacturer of the measuring instrument.

5. How we can describe measurement accuracy (cont-d)

- Indeed, if no such upper bound is known, this means that:
 - whatever the reading of the measuring instrument,
 - the actual value can be as far away from this reading as possible.
- So we get no information whatsoever about the actual value – in this case, this is not a measuring instrument, it is a wild guess.
- Ideally:
 - in addition to knowing that the measurement error Δx_i is somewhere in the interval $[-\Delta, \Delta]$,
 - it is desirable to know how probable are different values from this interval,
 - i.e., what is the probability distribution on the measurement error.
- Sometimes, we know this probability distribution.
- However, in many practical situations, we don't know it, and the upper bound is all we know.

6. How we can describe measurement accuracy (cont-d)

- So, we will consider this upper bound as the measure of the instrument's accuracy.
- This upper bound Δ may depend on the measured value.
- For example, suppose that we are measuring current in the range from 1 mA to 1 A.
- Then, it is relatively easy to maintain accuracy of 0.1 mA when the actual current is 1 mA.
- This means measuring with one correct decimal digit.
- We can get values 0.813..., 0.825...
- However, since the measurement accuracy is 0.1, this means that these measurement results may correspond to the same actual value.
- In other words, whatever the measuring instrument shows, only one digit is meaningful and significant.

7. How we can describe measurement accuracy (cont-d)

- All the other digits may be caused by measurement errors.
- But can we maintain the same accuracy of 0.1 mA when we measure currents close to 1 A?
- This would mean that we need to distinguish between values 0.94651 A = 946.51 mA and 0.94637 A = 946.37 mA.
- Indeed, the difference between these two values is larger than 0.1 mA.
- This would mean that we require that in the measurement result, we should have not one, but four significant digits.
- This would require much more accurate measurements.
- Because of this, we will explicitly take into account that the accuracy Δ depends on the measured value: $\Delta = \Delta(x)$.
- Usually, small changes in x lead to only small changes in the accuracy.
- So, we can safely assume that the dependence $\Delta(x)$ is smooth.

8. What we want

- We want to estimate the desired cumulative value x with some accuracy δ .
- In other words, we want to make sure that the difference between our estimate \tilde{x} and the actual value x does not exceed δ : $|\tilde{x} - x| \leq \delta$.
- The cumulative value is estimated based on n measurement results.
- As we have mentioned, the accuracy that we can achieve in each measurement, in general, depends on the measured value.
- The larger the value of the measured quantity, the more difficult it is to maintain the corresponding accuracy.
- It is therefore reasonable to conclude that:
 - whatever measuring instruments we use to measure each value x_i ,
 - it will be more difficult to estimate the larger cumulative value x with the same accuracy.

9. What we want (cont-d)

- Thus, it makes sense to require that the desired accuracy δ should also depend on the value that we want to estimate $\delta = \delta(x)$.
- The larger the value x , the larger the uncertainty $\delta(x)$ that we can achieve.
- So, our problem takes the following form:
- We want to be able to estimate the cumulative value x with given accuracy $\delta(x)$.
- In other words, we are given a function $\delta(x)$ and we want to estimate the cumulative value with this accuracy
- We want to find the measuring instruments:
 - that would guarantee this estimation accuracy, and
 - that would be optimal for this task, i.e., that would not provide better accuracy than needed.

10. Let us describe what we want in precise terms

- Let us analyze what estimation accuracy we can achieve if we use:
 - for each of n measurements,
 - the measuring instrument characterized by the accuracy $\Delta(x)$.
- Let \tilde{x}_i be the i -th measurement result.
- Then, the actual value x_i of the corresponding quantity is located somewhere on the interval $[\tilde{x}_i - \Delta(x_i), \tilde{x}_i + \Delta(x_i)]$.
- The smallest possible value is $\tilde{x}_i - \Delta(x_i)$.
- The largest possible value is $\tilde{x}_i + \Delta(x_i)$.
- When we add the measurement results, we get the estimate $\tilde{x} = \tilde{x}_1 + \dots + \tilde{x}_n$ for the desired quantity x .
- What are the possible values of this quantity?

11. Let us describe what we want in precise terms (cont-d)

- The sum $x = x_1 + \dots + x_n$ attains its smallest value if all values x_i are the smallest, i.e., when

$$x = (\tilde{x}_1 - \Delta(x_1)) + \dots + (\tilde{x}_n - \Delta(x_n)) = (\tilde{x}_1 + \dots + \tilde{x}_n) - (\Delta(x_1) + \dots + \Delta(x_n)).$$

- In this case, $x = \tilde{x} - (\Delta(x_1) + \dots + \Delta(x_n))$.
- Similarly, the sum $x = x_1 + \dots + x_n$ attains its largest value if all values x_i are the largest, i.e., when

$$x = (\tilde{x}_1 + \Delta(x_1)) + \dots + (\tilde{x}_n + \Delta(x_n)) = (\tilde{x}_1 + \dots + \tilde{x}_n) + (\Delta(x_1) + \dots + \Delta(x_n)).$$

- In this case, $x = \tilde{x} + (\Delta(x_1) + \dots + \Delta(x_n))$.
- Thus, all we can conclude about the value x is that this value belongs to the interval

$$[\tilde{x} - (\Delta(x_1) + \dots + \Delta(x_n)), \tilde{x} + (\Delta(x_1) + \dots + \Delta(x_n))].$$

- This means that we get an estimate of x with the accuracy

$$\Delta(x_1) + \dots + \Delta(x_n).$$

12. Let us describe what we want in precise terms (cont-d)

- Our objective is to make sure that this is exactly the desired accuracy $\delta(x)$.
- In other words, we want to make sure that whenever $x = x_1 + x_2 + \dots + x_n$, we should have $\delta(x) = \Delta(x_1) + \Delta(x_2) + \dots + \Delta(x_n)$.
- Substituting $x = x_1 + x_2 + \dots + x_n$ into this formula, we get

$$\delta(x_1 + x_2 + \dots + x_n) = \Delta(x_1) + \Delta(x_2) + \dots + \Delta(x_n).$$

- We do not know a priori what will be the values x_i .
- We want to maintain the desired accuracy $\delta(x)$ – and make sure that we do not get more accuracy.
- So, we should make sure that the equality be satisfied for all possible values x_1, x_2, \dots, x_n .

13. Let us describe what we want in precise terms (cont-d)

- In these terms, the problem takes the following form:
 - for which functions $\delta(x)$ is it possible to have a function $\Delta(x)$ for which the above equality is satisfied? and
 - how can we find this function $\Delta(x)$ – that describes the corresponding measuring instrument?
- This is the problem that we solve in this talk.

14. When Is Optimal Distributive Measurement of Cumulative Quantities Possible?

- We assumed that the function $\Delta(x)$ is smooth, i.e., differentiable.
- Thus, the sum $\delta(x)$ of such functions is differentiable too.
- Since both functions $\Delta(x)$ and $\delta(x)$ are differentiable, we can differentiate both sides of the above equality with respect to x_1 .
- The terms $\Delta(x_2), \dots, \Delta(x_n)$ do not depend on x_1 at all, so their derivative with respect to x_1 is 0.
- Thus, the resulting formula takes the form

$$\delta'(x_1 + x_2 + \dots + x_n) = \Delta'(x_1).$$

- Here, as usual, δ' and Δ' denote the derivatives of the corresponding functions.
- The new equality holds for all possible values x_2, \dots, x_n .
- For every real number x_0 , we can take, e.g., $x_2 = x_0 - x_1$ and $x_3 = \dots = x_n = 0$, then we will have $x_1 + x_2 + \dots + x_n = x_0$.

15. When Is Optimal Distributive Measurement of Cumulative Quantities Possible (cont-d)

- So, the equality takes the form $\delta'(x_0) = \Delta'(x_1)$.
- The right-hand side does not depend on x_0 , which means that the derivative $\delta'(x_0)$ is a constant not depending on x_0 either.
- The only functions whose derivative is a constant are linear functions.
- So we conclude that the dependence $\delta(x)$ is linear: $\delta(x) = a + b \cdot x$ for some constants a and b .
- Interestingly, this fits well with the usual description of measurement error, as consisting of two components:
 - the absolute error component a that does not depend on x at all,
 - and the relative error component.

16. When Is Optimal Distributive Measurement of Cumulative Quantities Possible (cont-d)

- For relative error, the bound on the measurement error is a certain percentage of the actual value x .
- So, it has the form $b \cdot x$ for some constant b .
- Example: 10% accuracy means $b = 0.1$. Thus, our result explains this usual description.

17. What Measuring Instrument Should We Select to Get the Optimal Distributive Measurement?

- Now we know for what desired accuracy $\delta(x)$, we can have the optimal distributive measurement of a cumulative quantity.
- The natural next question is:
 - given one of such functions $\delta(x)$,
 - what measuring instrument – i.e., what function $\Delta(x)$ – should we select for this optimal measurement?
- To answer this question, we can take $x_1 = \dots = x_n$.
- In this case, $\Delta(x_1) = \dots = \Delta(x_n)$, so the above equality takes the form $\delta(n \cdot x_1) = n \cdot \Delta(x_1)$.
- We know that $\delta(x) = a + b \cdot x$, so $a + b \cdot n \cdot x_1 = n \cdot \Delta(x_1)$.

18. What Measuring Instrument Should We Select to Get the Optimal Distributive Measurement (cont-d)

- If we divide both sides of this equality by n , and rename x_1 into x , we get the desired expression for $\Delta(x)$: $\Delta(x) = \frac{a}{n} + b \cdot x$.
- In other words:
 - the bound on the relative error component of each measuring instrument should be the same as for the cumulative quantity;
 - the bound on the absolute error component should be n times smaller than for the cumulative quantity.

19. Acknowledgments

- This work was supported in part by the National Science Foundation grants:
 - 1623190 (A Model of Change for Preparing a New Generation for Professional Practice in Computer Science), and
 - HRD-1834620 and HRD-2034030 (CAHSI Includes).
- It was also supported by the AT&T Fellowship in Information Technology.
- It was also supported by the program of the development of the Scientific-Educational Mathematical Center of Volga Federal District No. 075-02-2020-1478.